
1009 E Anthony St P.O. Box 768 Carroll, la 51401-3842



Performance Measure Targets - 2021 Performance Measure - Asset Type - Target % not in State of Good Repair

Equipment - Automobiles - 20%

Equipment - Trucks and other Rubber Tire Vehicles - 50% Facility - Administrative / Maintenance Facilities - 0%

Rolling Stock - AO - Automobile - 52%

Rolling Stock - BR - Over-the-road Bus - 0%

Rolling Stock - BU - Bus - 9%

Rolling Stock - CU - Cutaway - 43% Rolling Stock - MV - Minivan - 23%

Rolling Stock - VN - Van - 55%

at Maximum Service

Directly Operating Fare Purchased Mode Operated Transportation Expenses Revenues Demand Response 55 \$2,400,963 \$498,143 55 \$2,400,963 \$498.143 Total

Uses of Capital Funds	Annual Unlinked Trips	Annual Vehicle Revenue Miles	Annual Vehicle Revenue Hours
\$710,553	125,661	820,624	35,134

Performance Measures

Service Efficiency

Operating Expenses per Operating Expenses per Vehicle Revenue Mile Vehicle Revenue Hour Mode Demand Response \$2.93 \$68.34 Total \$2.93 \$68.34

Service Effectiveness O------

	per Unlinked	Unlinked Trips per	Unlinked Trips per
Mode	Passenger Trip	Vehicle Revenue Mile	Vehicle Revenue Hour
Demand Response	\$19.11	0.2	3.6
Total	\$19.11	0.2	3.6



