
SESDAC, Inc, dba: Vermillion Public Transit 2020 Annual Agency Profile

1314 E Cherry St Vermillion, Sd 57069-1606



Operation Characteristics


Vehicles Operated at Maximum Service

| | Directly | Purchased | Operating | Fare | Uses of Capital | | Annual Vehicle | Annual Vehicle |
|-----------------|----------|----------------|-----------|----------|-----------------|--------------|----------------|-----------------------|
| Mode | Operated | Transportation | Expenses | Revenues | Funds Annual Ur | linked Trips | Revenue Miles | Revenue Hours |
| Demand Response | 5 | - | \$505,495 | \$58,361 | \$31,698 | 33,753 | 66,500 | 5,625 |
| Total | 5 | - | \$505,495 | \$58,361 | \$31,698 | 33,753 | 66,500 | 5,625 |

Performance Measures

Service Efficiency

| | Service E | fficiency | | Service Effectiveness | | |
|-----------------|------------------------|------------------------|-----------------|-----------------------|----------------------|----------------------|
| | | | | Operating Expenses | | |
| | Operating Expenses per | Operating Expenses per | | per Unlinked | Unlinked Trips per | Unlinked Trips per |
| Mode | Vehicle Revenue Mile | Vehicle Revenue Hour | Mode | Passenger Trip | Vehicle Revenue Mile | Vehicle Revenue Hour |
| Demand Response | \$7.60 | \$89.87 | Demand Response | \$14.98 | 0.5 | 6.0 |
| Total | \$7.60 | \$89.87 | Total | \$14.98 | 0.5 | 6.0 |



Performance Measure Targets - 2021

Performance Measure - Asset Type - Target % not in State of Good Repair

Equipment - Automobiles - 40%

Equipment - Trucks and other Rubber Tire Vehicles - 40%

Facility - Administrative / Maintenance Facilities - 5%

Facility - Passenger / Parking Facilities - 0% Rolling Stock - AO - Automobile - 28%

Rolling Stock - BU - Bus - 28%

Rolling Stock - CU - Cutaway - 28%

Rolling Stock - MV - Minivan - 28%

Rolling Stock - SB - School Bus - 28%

Rolling Stock - SV - Sports Utility Vehicle - 28%

Rolling Stock - VN - Van - 28%