
119 S Lisbon St Ste 203 P.O. Box 185 Carrollton, Oh 44615-1448



Performance Measure Targets - 2022

Performance Measure - Asset Type - Target % not in State of Good Repair

Equipment - Automobiles - 30%

Equipment - Trucks and other Rubber Tire Vehicles - 0%

Facility - Administrative / Maintenance Facilities - 30%

Facility - Passenger / Parking Facilities - 0%

Rolling Stock - AO - Automobile - 30%

Rolling Stock - BU - Bus - 21%

Rolling Stock - CU - Cutaway - 2%

Rolling Stock - MV - Minivan - 10%

Rolling Stock - SV - Sports Utility Vehicle - 30%

Rolling Stock - VN - Van - 10%

Vehicles Operated

at Maximum Service

Directly Operating Fare Purchased Mode Operated Transportation Expenses Revenues Demand Response \$803,649 \$66,707 11 11 \$803.649 \$66,707 Total

Uses of Capital		Annual Vehicle	Annual Vehicle
Funds	Annual Unlinked Trips	Revenue Miles	Revenue Hours
\$87,730	6,180	263,447	8,679
\$87,730	6,180	263,447	8,679


Performance Measures

Service Efficiency

ModeVehicle Revenue MileVehicle Revenue HourDemand Response\$3.05\$92.60Total\$3.05\$92.60

	Service Effectiveness		
	Operating Expenses per Unlinked	Unlinked Trips per	Unlinked Trips per
Mode	Passenger Trip	Vehicle Revenue Mile	Vehicle Revenue Hour
Demand Response	\$130.04	0.0	0.7
Total	\$130.04	0.0	0.7

Operating Expense per Vehicle Revenue Mile: Agency Total





Unlinked Passenger Trips per Vehicle Revenue