
100 Lakemary Dr Paola, Ks 66071-1855



Performance Measure Targets - 2022

Performance Measure - Asset Type - Target % not in State of Good Repair

Equipment - Automobiles - 75%

Equipment - Trucks and other Rubber Tire Vehicles - 75%

Facility - Administrative / Maintenance Facilities - 25%

Facility - Passenger / Parking Facilities - 25%

Rolling Stock - BU - Bus - 25% Rolling Stock - CU - Cutaway - 25% Rolling Stock - MV - Minivan - 25%

Rolling Stock - VN - Van - 25%

Operation Characteristics

Vehicles Operated at Maximum Service

 Directly
 Purchased
 Operating
 Fare

 Mode
 Operated
 Transportation
 Expenses
 Revenues

 Demand Response
 3
 \$51,379
 \$5,371

 Total
 3
 \$51,379
 \$5,371

 Uses of Capital
 Annual Vehicle
 Annual Vehicle

 Funds
 Annual Unlinked Trips
 Revenue Miles
 Revenue Hours

 \$0
 1,410
 30,123
 883

 \$0
 1,410
 30,123
 883

Performance Measures

Service Efficiency

ModeOperating Expenses per
Vehicle Revenue MileOperating Expenses per
Vehicle Revenue MileOperating Expenses per
Vehicle Revenue HourDemand Response\$1.71\$58.19Total\$1.71\$58.19

	Service Effectiveness		
Mode	Operating Expenses per Unlinked Passenger Trip	Unlinked Trips per Vehicle Revenue Mile	Unlinked Trips per Vehicle Revenue Hour
Demand Response	\$36.44	0.0	1.6
Total	\$36.44	0.0	1.6



